



G:\My Drive\Epro Master Folder\Drafting\Details\Shoring\Novatak\50.302.1.1 BLIND VERTICAL ASSEMBLY - BACK LAGGING AT SOLDIER PILE (NON-HYDROSTATIC).dwg [Detail] July 09, 2021 - 8:13am

**BLINDSIDE VERTICAL ASSEMBLY - BACK LAGGING AT SOLDIER PILE (NON-HYDROSTATIC)**

	SYSTEM NAME	DRAWING NUMBER	
	NOVATAK	50.302.1.1	
	DRAFTER	DATE	
	RJT	07/01/2021	

AS A SUPPLIER OF FINISHED PRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1