


HYDROSTATIC CONDITIONS

FASTENED THROUGH 1/2" BALL OF NOVASEAL 5000 OR E.STOP GU WITH BROADHEAD NAIL OR FASTENER WITH WASHER


4"X4" NOVATAPE PATCH SEALED OVER FASTENER



NON-HYDROSTATIC CONDITIONS



BROADHEAD FASTENER OR FASTENER WITH WASHER

4"X4" NOVATAPE PATCH SEALED OVER FASTENER



G:\My Drive\Epro Master Folder\Drafting\Details\Shoring\Novatak\50.313.1 BLINDSIDE VERTICAL ASSEMBLY - REPAIR - FASTENERS (HYDROSTATIC & NON-HYDROSTATIC).dwg [Detail] July 01, 2021 - 9:53am

BLINDSIDE VERTICAL ASSEMBLY - REPAIR - FASTENERS (HYDROSTATIC & NON-HYDROSTATIC)

	SYSTEM NAME	DRAWING NUMBER	
	NOVATAK	50.313.1	
	DRAFTER	DATE	
	RJT	2/25/2021	

AS A SUPPLIER OF FINISHED PRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1