


HYDROSTATIC CONDITIONS

REINFORCE PATCH BY TAPING ALL EDGES WITH PRETAPE

BROADHEAD FASTENER OR FASTENER WITH WASHER SEALED WITH PM SEALANT


4"X4" PRETAK PATCH SEALED OVER FASTENER



NON-HYDROSTATIC CONDITIONS



BROADHEAD FASTENER OR FASTENER WITH WASHER

4"X4" PRETAPE PATCH SEALED OVER FASTENER



G:\My Drive\Epro Master Folder\Drafting\Details\Shoring\Pretak\51.313.1 BLINDSIDE VERTICAL ASSEMBLY - REPAIR - FASTENERS (HYDROSTATIC & NON-HYDROSTATIC).dwg [Detail] April 12, 2021 - 9:25am

BLINDSIDE VERTICAL ASSEMBLY - REPAIR - FASTENERS (HYDROSTATIC AND NON-HYDROSTATIC)

| | | | |
|---|-------------|----------------|---|
|  | SYSTEM NAME | DRAWING NUMBER |  |
| | PRETAK | 51.313.1 | |
| | DRAFTER | DATE | |
| | RJT | 3/17/2021 | |

AS A SUPPLIER OF FINISHED RPRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1