


FIELD SHEET OF PRIMETAK MEMBRANE

REPAIR DAMAGED AREAS, FISHMOUTHS, AND BLISTERS (LARGER THAN 4" IN DIAMETER). REMOVE ANY MATERIAL THAT DOES NOT ALLOW PATCH TO FULLY ADHERED OR LAY FLAT

PRIME EXPOSED SURFACE WITH PRIMETAK PRIMER. DO NOT PRIME SURFACE OF PRIMETAK MEMBRANE.



APPLY A PATCH OF PRIMETAK MEMBRANE 6" LARGER THAN DAMAGE IN ALL DIRECTIONS CENTERED OVER DAMAGED AREA .

BEAD OF PM SEALANT



G:\My Drive\Epro Master Folder\Drafting\Details\Decks\Primetak\55.480.1 PRIMETAK REPAIR - NON-HYDROSTATIC - SURFACE DAMAGE.dwg [Detail] April 27, 2021 - 9:06am

**PRIMETAK REPAIR - NON-HYDROSTATIC - SURFACE DAMAGE**

	SYSTEM NAME	DRAWING NUMBER	
	PRIMETAK	55.480.1	
	DRAFTER	DATE	
	RJT	4/05/2021	

AS A SUPPLIER OF FINISHED RPRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1