



G:\My Drive\Epro Master Folder\Drafting\Details\Underslab\E.Proformance M\15.170.1 UNDERSLAB VAPOR ASSEMBLY REPAIR.dwg [Detail] March 11, 2019 - 11:53am

**UNDERSLAB VAPOR ASSEMBLY REPAIR**

	SYSTEM NAME	DRAWING NUMBER	
	E.PROFORMANCE M	15.170.1	
	DRAFTER	DATE	
	TSH	03/11/19	

AS A SUPPLIER OF FINISHED RPRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1